



What year was your building constructed? 1975  
(Based on certificate of occupancy)

Total number of units per building: 68

Total number of floors per building: 9

ATTENTION: If this project includes buildings with multiple addresses, please complete and provide the "[Additional Building Address Form](#)" for each additional address.

Who completed your SIRS?

- Architect                       Engineer  
 Reserve Specialist               Qualified Person

Name of Individual that conducted the SIRS: Casey M. Ward

Name of Company that conducted the SIRS: Socotec

Total cost of the SIRS (not including assessment): 6500

Was there an assessment as a result of your association's SIRS?

- Yes     No

If yes, please provide the following information:

Total cost of the assessment: 3576800

Breakdown of cost per unit: 52600

The Structural Integrity Reserve Study (SIRS) was completed on: 12-27-24

The Structural Integrity Reserve Study (SIRS) was distributed to the unit owners by:

- Sent by Mail                       Electronic Transmission (E-mail)  
 Send by Personal Delivery       Facsimile Transmission

As per ss. 718.112(2)(g)9 &10, and 719.106(1)(k)9 & 10 F.S. The Structural Integrity Reserve Study must be available for inspection and copying by written request.

I hereby certify that the information provided in this form is true, accurate, and complete to the best of my knowledge.

Lloyd M Welker

Printed Name

*Lloyd M Welker*

Signature